

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number TXD008950461		2. Page 1 of 1/1	3. Emergency Response Phone 214-789-1627		4. Manifest Tracking Number 008252192 FLE		
		5. Generator's Name and Mailing Address US EPA Region 6/CES Environmental Site 1445 Ross Ave, STE 1200 Dallas, TX 75202-2733 Generator's Phone: 214-789-1627		Generator's Site Address (if different than mailing address) US EPA Region 6/CES Environmental Site 4904 Griggs Rd Houston, TX 77021					
6. Transporter 1 Company Name OIL PATCH TRANSPORTATION TIBC		U.S. EPA ID Number 38897 89396							
7. Transporter 2 Company Name		U.S. EPA ID Number							
8. Designated Facility Name and Site Address Lonestar Ecology, LLC 12901-A Bay Park Rd Pasadena, TX 77507 Facility's Phone: 281-204-1288		U.S. EPA ID Number TXD010791184							
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any)) 1. NA3082, Hazardous Waste Liquid N.O.S. (Benzene) 9. PGIII			10. Containers No. Type 001 T		11. Total Quantity 4900 G	12. Unit Wt./Vol. G	13. Waste Codes FXBC207H D018
14. Special Handling Instructions and Additional Information Job # 21388 1) Profile LSE1128 V5840 Truck: 510-903									
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.									
Generator's/Officer's Printed/Typed Name Larry Moore for EPA		Signature <i>[Signature]</i>		Month 3		Day 20		Year 15	
TRANSPORTER	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S.		Port of entry/exit: Date leaving U.S.:						
	17. Transporter Acknowledgment of Receipt of Materials								
	Transporter 1 Printed/Typed Name Michael Hsu		Signature <i>[Signature]</i>		Month 3		Day 20		
	Transporter 2 Printed/Typed Name		Signature		Month		Day		
DESIGNATED FACILITY	18. Discrepancy								
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection								
	Manifest Reference Number:								
	18b. Alternate Facility (or Generator)		U.S. EPA ID Number						
	Facility's Phone:								
	18c. Signature of Alternate Facility (or Generator)				Month		Day		
	19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)								
	1. H135	2.	3.	4.					
	20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a								
	Printed/Typed Name Antonio Inghart		Signature <i>[Signature]</i>		Month 3		Day 20		

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number <i>TXD008950461</i>		2. Page 1 of 1		3. Emergency Response Phone <i>214-789-1627</i>		4. Manifest Tracking Number 008252193 FLE	
		5. Generator's Name and Mailing Address <i>US EPA Region 8/CES Environmental Site 1445 Ross Ave, STE 1200 Dallas, TX 75202-2733</i>		Generator's Site Address (if different than mailing address) <i>US EPA Region 8/CES Environmental Site 4904 Griggs Rd Houston, TX 77034</i>					
Generator's Phone: <i>214-758-1627</i>		6. Transporter 1 Company Name <i>TIBC</i>		U.S. EPA ID Number <i>89396</i>					
7. Transporter 2 Company Name <i>ON-DUTY TRANSPORTATION</i>				U.S. EPA ID Number					
8. Designated Facility Name and Site Address <i>Lonestar Ecology, LLC 12901-A Bay Park Rd Pasadena, TX 77507</i>		Facility's Phone: <i>281-204-1260</i>		U.S. EPA ID Number <i>TXDQ10791184</i>					
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))			10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
					No.	Type			
		1. <i>NA3082, Hazardous Waste Liquid N.O.S. (Benzene) 9, PGIII</i>			<i>001</i>	<i>T</i>	<i>4900</i>	<i>12</i>	<i>FX9C207H D018</i>
		2.							
		3.							
	4.								
14. Special Handling Instructions and Additional Information <i>JOB # 21795 Truck: 510-909 1). Pumped off 5 1/2 tons</i>									
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.									
Generator's/Offor's Printed/Typed Name <i>GARY MOORE for EPA</i>					Signature <i>[Signature]</i>		Month Day Year <i>03 27 2015</i>		
TRANSPORTER INTL	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____								
	17. Transporter Acknowledgment of Receipt of Materials								
	Transporter 1 Printed/Typed Name <i>Michael Hsu</i>					Signature <i>[Signature]</i>		Month Day Year <i>3 27 15</i>	
	Transporter 2 Printed/Typed Name					Signature		Month Day Year	
DESIGNATED FACILITY	18. Discrepancy								
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection								
	18b. Alternate Facility (or Generator) _____ Manifest Reference Number: _____ U.S. EPA ID Number _____								
	Facility's Phone: _____								
	18c. Signature of Alternate Facility (or Generator) _____ Month Day Year _____								
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)									
1. <i>H135/H061</i>		2.		3.		4.			
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a									
Printed/Typed Name <i>Bruce Hechemann</i>					Signature <i>[Signature]</i>		Month Day Year <i>3 27 15</i>		

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number TXD008950451		2. Page 1 of 1/1	3. Emergency Response Phone 214-789-1627		4. Manifest Tracking Number 008252196 FLE			
		5. Generator's Name and Mailing Address US EPA Region 6/CES Environmental Site 1445 Ross Ave, STE 1200 Dallas, TX 75202-2733 Generator's Phone: 214-789-1627		Generator's Site Address (if different than mailing address) US EPA Region 6/CES Environmental Site 4804 Griggs Rd Houston, TX 77021						
6. Transporter 1 Company Name ENVIRONMENTAL TRANSPORTATION TIBC		U.S. EPA ID Number 00001 89396								
7. Transporter 2 Company Name		U.S. EPA ID Number								
8. Designated Facility Name and Site Address Lonestar Ecology, LLC 12901-A Bay Park Rd Pasadena, TX 77507 Facility's Phone: 281-204-1289		U.S. EPA ID Number TXD010791184								
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))			10. Containers No. Type		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes	
	1.	NA3082, Hazardous Waste Liquid N.O.S. (Benzene) 9, PGIII			1 T		4900 IG		FXBC207H D018	
	2.									
	3.									
	4.									
14. Special Handling Instructions and Additional Information Job # 21780 1) Profile LSE1128 VB010 Truck: 510-903										
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.										
Generator's/Offor's Printed/Typed Name: LARRY MOON for EPA Signature: <i>[Signature]</i> Month: 3 Day: 23 Year: 2015										
TRANSPORTER	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____									
	17. Transporter Acknowledgment of Receipt of Materials									
	Transporter 1 Printed/Typed Name: Michael Hsu Signature: <i>[Signature]</i> Month: 3 Day: 23 Year: 15									
Transporter 2 Printed/Typed Name: _____ Signature: _____ Month: _____ Day: _____ Year: _____										
DESIGNATED FACILITY	18. Discrepancy									
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection									
	Manifest Reference Number: _____									
	18b. Alternate Facility (or Generator) _____ U.S. EPA ID Number _____									
	Facility's Phone: _____									
18c. Signature of Alternate Facility (or Generator) _____ Month: _____ Day: _____ Year: _____										
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)										
1. H135 2. _____ 3. _____ 4. _____										
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a										
Printed/Typed Name: <i>[Signature]</i> Signature: <i>[Signature]</i> Month: 3 Day: 23 Year: 15										

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number	2. Page 1 of	3. Emergency Response Phone	4. Manifest Tracking Number
		TXDQ008950461	1/1	214-789-1827	008252197 FLE
5. Generator's Name and Mailing Address US EPA Region 6/CES Environmental Site 1445 Ross Ave, STE 1200 Dallas, TX 75202-2733 Generator's Phone: 214-789-1827					
Generator's Site Address (if different than mailing address) US EPA Region 6/CES Environmental Site 4904 Griggs Rd Houston, TX 77024					
6. Transporter 1 Company Name		7. Transporter 2 Company Name		U.S. EPA ID Number	
TIBK		TIBK		89396	
8. Designated Facility Name and Site Address Lonestar Ecology, LLC 12901-A Bay Park Rd Pasadena, TX 77507 Facility's Phone: 281-284-1260					
U.S. EPA ID Number TXDQ10791184					
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No. Type		11. Total Quantity	12. Unit Wt./Vol.
1.	NA3082, Hazardous Waste Liquid N.O.S. (Benzene) 9, PGIII	1 T		4,900 G	
2.					
3.					
4.					
13. Waste Codes FX8G207H D018					
14. Special Handling Instructions and Additional Information Job #21781 1) Profile LSE1128 VPS40 FT 3033A Truck: 510-903					
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.					
Generator's/Officer's Printed/Typed Name		Signature		Month Day Year	
GARY MOORE FOR EPA		[Signature]		3 25 15	
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: Date leaving U.S.:					
17. Transporter Acknowledgment of Receipt of Materials					
Transporter 1 Printed/Typed Name		Signature		Month Day Year	
Michael Hsu		[Signature]		3 25 15	
Transporter 2 Printed/Typed Name		Signature		Month Day Year	
18. Discrepancy					
18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection					
Manifest Reference Number:					
18b. Alternate Facility (or Generator) U.S. EPA ID Number					
Facility's Phone:					
18c. Signature of Alternate Facility (or Generator) Month Day Year					
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)					
1. H135		2.		3.	
				4.	
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a					
Printed/Typed Name		Signature		Month Day Year	
[Signature]		[Signature]		3 25 15	